

# General Environmental Incident Summary

**Incident:** 3565      **Date/Time Notice:** 11/25/2014      1100      **DEM Incident No:**  
**Responsible Party:** Otto Transfer, Inc.  
**Date Incident:** 11/25/2014      **Time Incident:** 0900      **Duration:** 1 hours  
**County:** Ward      **Twp:** 155      **Rng:** 83      **Sec:** 22      **Qtr:**  
**Lat:** 48.23296      **Long:** -101.31860      **Method:** Interpolation from map  
**Location Description:** XCEL yard, 300 16th ST SW, MINOT, ND near pole bunk

**Submitted By:** Kevin Otto      **Affiliation:**  
**Address:** 3665 57th ST SE  
**City:** Delano      **State:** MN      **Zip:** 55328

## Received By:

**Contact Person:** Kevin otto  
3665 57th ST SE  
Delano, MN 55328

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** hydraulic line break

**Description of Released Contaminant:** aw32 hydraulic oil

**Volume Spilled:** 20.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

failure of hydraulic line

## Risk Evaluation:

none

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 09 - other

## Potential Environmental Impacts:

none

## Action Taken or Planned:

On asphalt, contained with absorbent pads and cleaned up with floor dry

**Wastes Disposal Location:** NSP contractor

## Agencies Involved:

## ***Updates***

---

***Date:*** 11/25/2014   ***Status:*** Reviewed - No Action Required

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Small volume hydraulic line leak was contained and cleaned up. No on-site inspection necessary.